

GVM-10 Quick Start User Guide

- Connect the tri-axial geophone sensor unit and place it in position ensuring that it is level.
- Press the green ON key.
- To start monitoring, press the top right hand Bar-graph key. The GVM-10 will test each geophone and begin monitoring and display the results. After 2 minutes the screen will go blank to save battery life. Press the Bulb key to re-activate the display.
- To stop monitoring, press the top right hand Bar-graph key and the data will be written to the SD card.
- Full instructions are set out in the GVM-10's manual along with the analysis software on the memory stick supplied with the GVM-10.

Accudata Ltd
Aspect House
48 The Spinney
Ripley, Derbyshire
DE5 3HW
Telephone: 01773 513222
Email: info@accudata.co.uk
Website: www.accudata.co.uk